



ARCHITECTURAL/HISTORICAL COMPONENT FORM

**IMPORTANT:** USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

1) Resource No 5CF270 2) Temp No. 59 3) Name Band Box Cleaners  
4) Address 119 North F 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good  Fair  Deteriorated

7) Original Use commercial property 8) Present Use commercial property

9) Original Site  Moved  Date(s) of Move: \_\_\_\_\_

10) Unaltered  Altered  Explain: Brick siding over kickplates (panels  
beneath display area)

II. DESCRIPTION: 11) Building Materials brick/metal cornice

12) Construction Date 1890-1893 13) Architect/Builder unknown  
(1890, 1893 Sanborn Maps)

14) Architectural Style(s) n/a

15) Special Features/Surroundings: See resource no. 5CF263

16) Archaeological Potential: Yes  No  Unknown  Explain: \_\_\_\_\_

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce		
18) SUB-THEME	Trade		
19) TYPES	commercial structure		

(Attach Photographs)

Frame Number 9  
 Roll Number CF4  
 Facade Orientation W

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

A two story brick commercial building featuring six segmental arch bays, the bracketed metal cornice which connects the building to its neighbors, and a continuous lintel separating the storefront area from the upper story. On the ground level are two recessed entrances flanked by display windows and highlighted above by a transom window. A side entrance to the second story is also evident.

In 1893 the structure housed a saloon and a clothing store.

(note: The northern half of the building was begun as early as 1890, for it is listed on the 1890 map as "being built".)

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1890, 1893 Sanborn Perris Maps



Band Box  
COIN OPERATED  
LAUNDRY

BAND BOX  
LAUNDRY

P

ORS