



ARCHITECTURAL/HISTORICAL COMPONENT FORM

**IMPORTANT:** USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

- 1) Resource No. 5CF245 2) Temp No. 34 3) Name part of Stallsworth Motor Co. Datsun Dealership  
 4) Address 139 W. Third 5) District Name n/a  
 I. **INTEGRITY:** 6) Condition: Good  Fair  Deteriorated   
 7) Original Use commercial property 8) Present Use commercial property  
 9) Original Site  Moved  Date(s) of Move: \_\_\_\_\_  
 10) Unaltered  Altered  Explain: Display windows partially covered.

- II. **DESCRIPTION:** 11) Building Materials brick  
 12) Construction Date 1904-1914 13) Architect/Builder unknown  
 14) Architectural Style(s) (1904, 1914 Sanborn Perris maps) n/a  
 15) Special Features/Surroundings: n/a

- 16) Archaeological Potential: Yes  No  Unknown  Explain: \_\_\_\_\_

III. **CULTURAL ACTIVITIES:** Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce	
18) SUB-THEME	Retail/Wholesale/Trades	
19) TYPES	commercial structure	

(Attach Photographs)

Frame Number 3  
 Roll Number CF 3  
 Facade Orientation N

**IV. SIGNIFICANCE:** Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

A two story brick structure distinguished by brickwork patterns at the roofline, four segmental arch openings on the second floor, and an intact storefront area. The large display windows which are partially covered are highlighted by cut stone lintels.

In 1914 the building housed offices, a garage, and a machine shop.

22) List Any Associated Cultural Group: n/a

**V. REFERENCES:**

1. 1914 Sanborn Perris map

INVENTORY RECORD

NOT FOR FIELD USE <input type="checkbox"/> DET. ELIG. <input type="checkbox"/> DET. NOT ELIG. <input type="checkbox"/> NOMINATED LISTED, DATE _____
---



IMPORTANT: COMPLETE THIS SHEET FOR EACH RESOURCE PLUS EITHER AN ARCHAEOLOGICAL OR HISTORICAL/ARCHITECTURAL COMPONENT FORM.

I. IDENTIFICATION: 1)Resource No. 5CF245 2)Temp. No. 34

3)Resource Name part of Stallsworth 4)Project Name FCRC Survey

Motor Co./Datsun Dealership

5)Category: Arch. Site , Hist./Archit. Structure , Hist./Archit. District .

6)(For Arch. site)In a District:yes  no  ;Name \_\_\_\_\_

II. LOCATION: 7)Township 50N ;Range 9E ; SE  $\frac{1}{4}$  of SW  $\frac{1}{4}$  of SW  $\frac{1}{4}$  of SE  $\frac{1}{4}$  of

Section 32 ; P.M. New Mexico . 8)County Chaffee

9)USGS QUAD Cameron Mountain ;7.5 15 X;Date 1956 Attach photocopy

portion of Quad. Clearly show site. 10)Other maps 1929 Sanborn Perris Map

11)Dimensions 15.15mX 37.9 m 12)Area 574.2 sq.m(+4047=) .14 acres

13)UTM Reference: (One UTM centered on resource may be given for resource under 10 acres.)

A. | 1,3 | ; | 4,1,3 | 3,5,0 | mE; | 4,2,6,5 | 4,2,0 | mN. B. | | | ; | | | | | | mE; | | | | | | mN.

C. | | | ; | | | | | | mE; | | | | | | mN. D. | | | ; | | | | | | mE; | | | | | | mN.

14)Address 139 W. Third Lot <sup>22-26</sup>~~26~~ Block 49 Addition Haskell's Addition

III. MANAGEMENT DATA: 15)Field Assessment: Eligible  Not Eligible  Need Data

16)Owner/Address Floyd and Elsie Stallsworth, Salida ,

17)Gov't Involvement: County  State  Federal  Private  : Agency n/a

18)Disturbance:none  light  moderate  heavy  total  ;Explain Display windows

partially covered

19)Threats to Resource:Water Erosion  Wind Erosion  Animal Activity  Neglect  Vandalism

Recreation  Construction  ;Comments n/a

20)Management Recommendations Refer to Secretary of the Interior's

Standards for Rehabilitation

V. REFERENCE: 21)State/Fed. Permit Nos. n/a

22)Photo Nos. CF3/3 ,on file at CPO

Historical Surveys of Colorado Communities: Upper Arkansas Valley,

23)Report Title Salida


24)Recorder M. Taylor 25)Recording Date 6/15/81

26)Recorder Affiliation CPO/FCRC Survey 27)Phone No. 866-3392

V. SKETCH MAP: Map all features and show the boundaries of the resources. Show all major topographic features, permanent modern features, and vegetation zones as appropriate. Give names of features, streets and addresses if known. Provide scale, key and direction.

scale:

key:



28) Location/Access:

n/a

29) Boundary Description:

n/a

30) Boundary Justification:


n/a



50F245 ←

(BONANZA)  
4760 I

Mapped, edited, and published by the Geological Survey  
 Control by USGS and USC&GS  
 Topography from aerial photographs by photogrammetric methods  
 Aerial photographs taken 1953. Field check 1956  
 Polyconic projection 1927 North American datum  
 10,000 foot grid based on Colorado coordinate system,  
 central zone  
 1000 meter Universal Transverse Mercator grid ticks,  
 zone 13, shown in blue  
 Red tint indicates area in which only  
 landmark buildings are shown  
 Land lines in Ts 49, 50 and 51 N - Rs 9, 10 and 11 E.



CONTOUR INTERVAL 40  
 NATIONAL GEODETIC VERTICAL D

SCALE 1:62500

UTM GRID AND 1956 MAGNETIC NORTH  
 DECLINATION AT CENTER OF SHEET

THIS MAP COMPLIES WITH NATIONAL



DATSUN  
SALES-PARTS  
SERVICE

D  
A  
T  
S  
U  
N

UN  
COPY  
IF  
LINE