



ARCHITECTURAL/HISTORICAL COMPONENT FORM

**IMPORTANT:** USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

- 1) Resource No. 5CF285 2) Temp No. 74 3) Name Sherman Hotel (Job Service/ Drug and Alcohol Abuse)  
 4) Address 149 W. First St. 5) District Name n/a
- I. **INTEGRITY:** 6) Condition: Good  Fair  Deteriorated   
 7) Original Use commercial property 8) Present Use commercial property  
 9) Original Site  Moved  Date(s) of Move: \_\_\_\_\_  
 10) Unaltered  Altered  Explain: Window alterations, brick over kickplates (area beneath display windows).

- II. **DESCRIPTION:** 11) Building Materials brick  
 12) Construction Date 1909-1914 13) Architect/Builder unknown  
 (1909, 1914 Sanborn Perris maps)  
 14) Architectural Style(s) n/a  
 15) Special Features/Surroundings: n/a

- 16) Archaeological Potential: Yes  No  Unknown  Explain: \_\_\_\_\_

III. **CULTURAL ACTIVITIES:** Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Public/Government		
18) SUB-THEME	Services		
19) TYPES	commercial structure (offices)		



(Attach Photographs)

Frame Number 5  
Roll Number CF 5  
Facade Orientation N,E

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

21) Historical Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

This rectangular two story brick structure initially housed a saloon and restaurant. The building is characterized by a simple brickwork design at the cornice line and more elaborate brick pattern (visible on the G Street facade) separating the first and second stories. The storefronts on First Street have been modified to accommodate office space.

In c. 1929 the building was connected to its neighbor to the south, resource no. 5CF286, and became part of the Sherman Hotel.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1914, 1929 Sanborn Perris maps

BY M. Taylor

DATE 6-15-81





INVENTORY RECORD

IMPORTANT: COMPLETE THIS SHEET FOR EACH RESOURCE PLUS EITHER AN ARCHAEOLOGICAL OR HISTORICAL/ARCHITECTURAL COMPONENT FORM.

NOT FOR FIELD USE
DET. ELIG.
DET. NOT ELIG.
NOMINATED
LISTED, DATE _____

I. IDENTIFICATION: 1)Resource No. 5CF285 2)Temp. No. 74

3)Resource Name Sherman Hotel 4)Project Name FCRC Survey

5)Category: Arch. Site   , Hist./Archit. Structure X, Hist./Archit. District   .

6)(For Arch. site)In a District:yes no ;Name   

II. LOCATION: 7)Township 50 N ;Range 9E ; SE  $\frac{1}{4}$  of NE  $\frac{1}{4}$  of SW  $\frac{1}{4}$  of SE  $\frac{1}{4}$  of

Section 32 ; P.M. New Mexico . 8)County Chaffee

Principal Meridian

9)USGS QUAD Cameron Mountain ;7.5 15X ;Date 1956 Attach photocopy

portion of Quad. Clearly show site. 10)Other maps 1929 Sanborn Perris Map

11)Dimensions 22.7 mX 45.5 m 12)Area 1032.8 sq.m(+4047=) .25 acres

13)UTM Reference: (One UTM centered on resource may be given for resource under 10 acres.)

A. 1,3 ; 4 | 1,3 | 5,0,0 | mE ; 4,2 | 6,5 | 6,0,0 | mN. B.    ;    |    |    | mE ;    |    |    | mN.

C.    ;    |    |    | mE ;    |    |    | mN. D.    ;    |    |    | mE ;    |    |    | mN.

11-13

4)Address 149 W. First St. Lot    Block 21 Addition Salida Tract

III. MANAGEMENT DATA: 15)Field Assessment: Eligible    Not Eligible X Need Data   

16)Owner/Address John & Ricarda Evans/ Clyde & Edna McCargan, Salida

17)Gov't Involvement: County    State    Federal    Private    ; Agency government offices

18)Disturbance: none    light X moderate    heavy    total    ; Explain Window modifications

ound floor; brick over kickplates (panels beneath display windows)

19)Threats to Resource: Water Erosion    Wind Erosion    Animal Activity    Neglect    Vandalism   

Recreation    Construction    ; Comments n/a

20)Management Recommendations Refer to Secretary of the Interior's Standards  
for Rehabilitations

V. REFERENCE: 21)State/Fed. Permit Nos. n/a

22)Photo Nos. CF5/5 , on file at CPO


23)Report Title Historical Surveys of Colorado Communities: Upper Arkansas  
Valley, Salida

24)Recorder M. Taylor 25)Recording Date 6/15/81

26)Recorder Affiliation FCRC Survey/CPO 27)Phone No. 866-3392



V. SKETCH MAP: Map all features and show the boundaries of the resources. Show all major topographic features, permanent modern features, and vegetation zones as appropriate. Give names of features, streets and addresses if known. Provide scale, key and direction.



28) Location/Access:

n/a

29) Boundary Description:

n/a

30) Boundary Justification:

n/a



5CF285

IBONANZA  
4760 I



Mapped, edited, and published by the Geological Survey  
 Control by USGS and USC&GS  
 Topography from aerial photographs by photogrammetric methods  
 Aerial photographs taken 1953. Field check 1956  
 Polyconic projection. 1927 North American datum.  
 10,000 foot grid based on Colorado coordinate system,  
 central zone  
 1000 meter Universal Transverse Mercator grid ticks,  
 zone 13, shown in blue  
 Red tint indicates area in which only  
 landmark buildings are shown  
 Land lines in T<sub>s</sub> 49, 50 and 51 N - R<sub>s</sub> 9, 10 and 11 E.  
 based on the 1899 Meridian. Original Map 500

UTM GRID AND 1956 MAGNETIC NORTH  
 DECLINATION AT CENTER OF SHEET

0° 11' 10" MILS  
 14' 24" MILS

SCALE 1:62,500

CONTOUR INTERVAL 40  
 NATIONAL GEODETIC VERTICAL I

THIS MAP COMPLIES WITH NATIONAL MA



