

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1 of 3

Date _____ Initials _____
_____ Determined Eligible-NR
_____ Determined Not Eligible-NR
_____ Determined Eligible-SR
_____ Determined Not Eligible-SR
_____ Need Data
_____ Contributes to Eligible NR District
_____ Noncontributing to Eligible NR District

I. IDENTIFICATION

1. **Resource Number:** 5CF406.8
2. **Temporary Resource Number:** 39
3. **County:** Chaffee
4. **City:** Salida
5. **Historic Building Name:** Vail Block, Sam Romeo Saloon, Witham Rooms
6. **Current Building Name:** La Frontera Restaurant
7. **Building Address:** 128 N. F St.
8. **Owner Name and Address:** Bernick, Philip A., 1115 Taylor Ave., Idaho Falls, ID 83404

Parcel Number: 368132405095
SHF Grant Number: 2001-02-004

II. GEOGRAPHIC INFORMATION

9. **P.M.** N.M. **Township** 50N **Range** 9E
1/4 1/4 SE 1/4 SE 1/4 **of Section** 32
10. **UTM Reference**
Zone 13 **Easting** 413623 **Northing** 4265637
11. **USGS Quad Name:** Salida East, Colo.
Year: 1994 **Map Scale:** 7.5' Attach photo copy of appropriate map section.
12. **Lot (s):** 1-2 (part) **Block(s):** 5
Addition: Salida Original Townsite **Year of Addition:** 1880
13. **Boundary Description and Justification:**
Boundary includes the building and the urban parcel on which it is situated.

III. ARCHITECTURAL DESCRIPTION

14. **Building Plan (footprint, shape):** Rectangular
15. **Dimensions in Feet: Length** 64 **X Width** 21
16. **Stories:** 1
17. **Primary External Wall Material(s) (enter no more than two):**
Brick
18. **Roof Configuration (enter no more than one):**
Flat
19. **Primary External Roof Material (enter no more than one):** Asphalt
20. **Special Features (enter all that apply):**
Decorative Cornice, Chimneys
21. **General Architectural Description:**

One-story, rectangular, brick and concrete block commercial building with flat roof stepped down toward rear. Façade clad in red brick has cornice of multiple narrow corbelled bands of brick. Brick end piers enframe façade. Band of decorative brickwork with bricks on end above continuous clerestory. Continuous lintel below clerestory. Plate glass windows with brick under windows. Center inset entrance with angled walls flanking paneled and glazed door. Painted brick south wall is adjacent to alley. Storefront design continues for one bay on south wall. Two brick chimneys with metal tops visible on south. North wall is adjacent open lot, and is painted concrete block with murals

and French doors. Shed roof frame addition on rear.

22. **Architectural Style/Building Type:** Late 19th and Early 20th Century American Movements/Commercial Style

23. **Landscaping or Special Setting Features:**

N/A

24. **Associated Buildings, Features, or Objects:**

None

IV. ARCHITECTURAL HISTORY

25. **Date of Construction:** Estimate 1890-93 **Actual**

Source of Information: Sanborn maps, 1890 and 1893

26. **Architect:** Unknown

Source of Information:

27. **Builder/Contractor:** Unknown

Source of Information:

28. **Original Owner:** Unknown

Source of Information:

29. **Construction History (include description and dates of major additions, alterations, or demolitions):**

The current building represents only a small portion of the original building. The building is not shown on the 1890 Sanborn, when a smaller one-story structure was located here. In 1893 the original building appears on the Sanborn, a large two-story business block with three storefronts. The 1945 Sanborn map shows the original building. The building was heavily damaged in a fire in 1948, leaving only the present part of the building, which was also partially rebuilt.

30. **Original Location:** Yes **Date of Moves**

V. HISTORICAL ASSOCIATIONS

31. **Original Use(s):** Commerce and Trade/Restaurant/Bar

32. **Intermediate Use(s):** Commerce and Trade/Specialty Store

33. **Current Use(s):** Commerce and Trade/Restaurant

34. **Site Type(s):** Commercial Building

35. **Historical Background:**

This building was erected between 1890 and 1893. The 1890 Sanborn map shows a different, smaller, one-story saloon on this parcel. By 1893 the current building is shown, although it was originally a much larger two-story building. The building is shown housing a saloon on Sanborn maps of 1893, 1898, 1904, and 1909. The 1903-04 city directory indicates that this building was known as the Vail Block. In that year the building housed Sam Romeo Saloon (Romeo also lived here) and furnished rooms operated by Mrs. Mary C. Witham. In 1905-06 the Louis Dalla Saloon was listed here, together with the furnished rooms run by Mary Witham. The 1909 city directory listed the Silver Dollar Saloon (operated by Nick Muto and Anton Presta) at this address. The 1914 Sanborn map indicated that the building housed a billiard parlor and confectionery in the space of the present building. By 1927-28, Mrs. Josephine Botz operated a restaurant here. In 1930-31, this was the location of the New Grand Café, managed by Sim Wong. On 10 March 1948 the Salida Mail reported that Louis Schneider's building had been gutted by fire. Damages were estimated at \$60,000. The paper reported that the Albany Hotel and the M&O Poolroom were ruined and heavy damage was sustained by General Auto Supply and the Stancati Liquor Store. By 1951, Frank Stancati operated a liquor store here in the rebuilt, smaller building, Stancati Liquor.

36. **Sources of Information:**

Chaffee County Assessor records; Salida City Directories; Sanborn Insurance Maps; Salida Walking Tours; Survey Form, 128 N. F St., 1981; Salida Mail, 10 March 1948.

VI. SIGNIFICANCE

37. Local Landmark Designation: No Date of Designation:

Designating Authority:

38. Applicable National Register Criteria:

- A. Associated with events that have made a significant contribution to the broad pattern of our history;
 - B. Associated with the lives of persons significant in our past;
 - C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possesses high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
 - D. Has yielded, or may be likely to yield, information important to history or prehistory.
- Qualifies under Criteria Considerations A through G (See Manual).

X Does not meet any of the above National Register criteria.

39. Area(s) of Significance:

40. Period of Significance:

41. Level of Significance:

42. Statement of Significance:

This building represents a small part of a larger historic building on this site, most of which was destroyed by fire in the 1940s. The present appearance of the building dates to 1948, which falls outside the district's period of significance.

43. Assessment of Historic Physical Integrity Related to Significance:

The building's current appearance represents its 1948 remodeling; it was once a small part of a much larger building.

VII. NATIONAL REGISTER ELIGIBILITY ASSESSMENT

44. National Register Field Eligibility Assessment: Not eligible

45. Is there National Register district potential? Discuss. N/A

This building is located within an existing National Register District, the Salida Downtown Historic District.

If there is NRHP district potential, indicate contributing status: N/A

46. If the building is in an existing NRHP district, indicate contributing status: Noncontributing

VIII. RECORDING INFORMATION

47. Photographic Reference(s): 4, 7, 9, 11, 13.

Negatives Filed At: City of Salida

Photographer: Roger Whitacre

48. Report Title: Downtown Salida Historic Buildings Survey, 2001-02

49. Date(s): September 2002 50. Recorder(s): R.L. Simmons/T.H. Simmons

51. Organization: Front Range Research Associates, Inc.


52. Address: 3635 W. 46th Ave.

53. Phone Number(s): (303) 477-7597

NOTE: Please attach a sketch map, a photocopy of the USGS quad map indicating the resource's location, and photographs.

Colorado Historical Society-Office of Archaeology and Historic Preservation
1300 Broadway, Denver, Colorado 80203 (303) 866-3395

Downtown Salida Historic Buildings Survey, 2001-02
Sketch Map




128 N. F Street, 5CF406.8



Downtown Salida Historic Buildings Survey, 2001-02
USGS Location Map

128 N F St, 5CF406.8



Mosaic of extracts from U.S. Geological Survey, "Salida East, Colo.," and "Salida West, Colo.," (Denver, Colo.: U.S. Geological Survey, 1994).

