

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1 of 3

Date _____	Initials _____
_____	Determined Eligible-NR
_____	Determined Not Eligible-NR
_____	Determined Eligible-SR
_____	Determined Not Eligible-SR
_____	Need Data
_____	Contributes to Eligible NR District
_____	Noncontributing to Eligible NR District

I. IDENTIFICATION

1. Resource Number: 5CF406.51
2. Temporary Resource Number: 62
3. County: Chaffee
4. City: Salida
5. Historic Building Name: Continental Trailways Bus Station
6. Current Building Name: Alliance Against Domestic Abuse
7. Building Address: 120 E. 1st St.
8. Owner Name and Address: Cook, William (2/5 int.), et al, P.O. Box 523, Salida, CO 81201

Parcel Number: 368132404089
SHF Grant Number: 2001-02-004

II. GEOGRAPHIC INFORMATION

9. P.M. N.M. Township 50N Range 9E
1/4 1/4 SE 1/4 SE 1/4 of Section 32

10. UTM Reference
Zone 13 Easting 413654 Northing 4265564

11. USGS Quad Name: Salida East, Colo.
Year: 1994 Map Scale: 7.5' Attach photo copy of appropriate map section.

12. Lot (s): 19 Block(s): 4
Addition: Salida Original Townsite Year of Addition: 1880

13. Boundary Description and Justification:
Boundary includes the building and the urban parcel on which it is situated.

III. ARCHITECTURAL DESCRIPTION

14. Building Plan (footprint, shape): Rectangular
15. Dimensions in Feet: Length 70 X Width 30
16. Stories: 1
17. Primary External Wall Material(s) (enter no more than two):
Brick Concrete/Concrete Block
18. Roof Configuration (enter no more than one):
Flat
19. Primary External Roof Material (enter no more than one): Asphalt
20. Special Features (enter all that apply):
Porch
21. General Architectural Description:

One-story rectangular red brick and concrete block building with flat roof which projects outward on the east to create a sheltered area under overhang. Metal coping. Band of vertically sawn paneling on upper south wall. East wall is painted concrete block. Façade (red brick) has center entrance with metal frame glazed door flanked by two large plate glass windows with brick sills. East wall has plate glass window with brick sill and three pedestrian doors.

22. Architectural Style/Building Type: No Style

23. Landscaping or Special Setting Features:

N/A

24. Associated Buildings, Features, or Objects:

None

IV. ARCHITECTURAL HISTORY**25. Date of Construction: Estimate****Actual 1973**

Source of Information: Chaffee County Assessor

26. Architect: Unknown

Source of Information:

27. Builder/Contractor: Unknown

Source of Information:

28. Original Owner: Unknown

Source of Information:

29. Construction History (include description and dates of major additions, alterations, or demolitions):

This building was constructed in 1973.

30. Original Location: Yes**Date of Moves****V. HISTORICAL ASSOCIATIONS****31. Original Use(s):** Transportation/Road-Related (Vehicular)**32. Intermediate Use(s):** Transportation/Road-Related (Vehicular)**33. Current Use(s):** Other Use**34. Site Type(s):** Bus Station**35. Historical Background:**

This building was erected in 1973 as a bus station utilized by Continental Trailways Bus Company. Today the building houses Alliance Against Domestic Abuse.

36. Sources of Information:

Chaffee County Assessor records; Salida City Directories; Sanborn Insurance Maps; Survey Form, 120 E. 1st St., 1981.

VI. SIGNIFICANCE**37. Local Landmark Designation: No****Date of Designation:****Designating Authority:****38. Applicable National Register Criteria:**

- A. Associated with events that have made a significant contribution to the broad pattern of our history;
 - B. Associated with the lives of persons significant in our past;
 - C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possesses high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
 - D. Has yielded, or may be likely to yield, information important to history or prehistory.
- Qualifies under Criteria Considerations A through G (See Manual).

X Does not meet any of the above National Register criteria.

39. Area(s) of Significance:**40. Period of Significance:****41. Level of Significance:****42. Statement of Significance:**

This building is less than fifty years old and has not yet achieved historical significance. It was built after the period of significance for the district.

43. Assessment of Historic Physical Integrity Related to Significance:

The building appears to be unaltered.

vii. NATIONAL REGISTER ELIGIBILITY ASSESSMENT

44. National Register Field Eligibility Assessment: Not eligible

45. Is there National Register district potential? Discuss. N/A

This building is located within an existing National Register district, the Salida Downtown Historic District.

If there is NRHP district potential, indicate contributing status: N/A

46. If the building is in an existing NRHP district, indicate contributing status: Noncontributing

VIII. RECORDING INFORMATION

47. Photographic Reference(s): 22: 8, 10; 23: 21.

Negatives Filed At: City of Salida

Photographer: Roger Whitacre

48. Report Title: Downtown Salida Historic Buildings Survey, 2001-02

49. Date(s): September 2002

50. Recorder(s): R.L. Simmons/T.H. Simmons

51. Organization: Front Range Research Associates, Inc.

52. Address: 3635 W. 46th Ave.

53. Phone Number(s): (303) 477-7597

NOTE: Please attach a sketch map, a photocopy of the USGS quad map indicating the resource's location, and photographs.

**Colorado Historical Society-Office of Archaeology and Historic Preservation
1300 Broadway, Denver, Colorado 80203 (303) 866-3395**

Downtown Salida Historic Buildings Survey, 2001-02
Sketch Map




120 E. 1st Street, 5CF406.51



Downtown Salida Historic Buildings Survey, 2001-02
USGS Location Map

120 E 1st St, 5CF406.51



Mosaic of extracts from U.S. Geological Survey, "Salida East, Colo.," and "Salida West, Colo.," (Denver, Colo.: U.S. Geological Survey, 1994).

