

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1 of 3

Date _____	Initials _____
_____	Determined Eligible-NR
_____	Determined Not Eligible-NR
_____	Determined Eligible-SR
_____	Determined Not Eligible-SR
_____	Need Data
_____	Contributes to Eligible NR District
_____	Noncontributing to Eligible NR District

I. IDENTIFICATION

1. Resource Number: 5CF406.70
2. Temporary Resource Number: 95
3. County: Chaffee
4. City: Salida
5. Historic Building Name: Salida Service Station
6. Current Building Name: Green Cat
7. Building Address: 124 G St.
8. Owner Name and Address: Brady, Stephen & Joe, P.O. Box 82, Coaldale, CO 81222

Parcel Number: 368132420365
SHF Grant Number: 2001-02-004

II. GEOGRAPHIC INFORMATION

9. P.M. N.M. Township 50N Range 9E
1/4 1/4 SW 1/4 SE 1/4 of Section 32

10. UTM Reference

Zone 13 Easting 413468 Northing 4265618

11. USGS Quad Name: Salida East, Colo.

Year: 1994 Map Scale: 7.5' Attach photo copy of appropriate map section.

12. Lot (s): 1-2 (part)

Block(s): 20

Addition: Salida Original Townsite

Year of Addition: 1880

13. Boundary Description and Justification:

Boundary includes the building and the urban parcel on which it is situated.

III. ARCHITECTURAL DESCRIPTION

14. Building Plan (footprint, shape): Rectangular

15. Dimensions in Feet: Length 73 X Width 24

16. Stories: 2

17. Primary External Wall Material(s) (enter no more than two):

Brick

18. Roof Configuration (enter no more than one):

Flat

19. Primary External Roof Material (enter no more than one): Asphalt

20. Special Features (enter all that apply):

Segmental Arch Windows, Fence, Chimney

21. General Architectural Description:

Two-story rectangular painted brick commercial building with flat roof with projecting brick coping. Brick piers enframe building and there is a projecting course of brick above the second story windows. At each end of the second story are small 4-light segmental arched windows with wood sills. The first story has a wood lintel and a center, inset entrance with wood door with large rectangular light and transom. Walls adjacent the door are angled inward and there are plate glass display windows with brick below. The storefront wraps to the north wall, which has a plate glass display window and wood door with large rectangular light and transom. Toward the rear of the two-

story section are double doors covered with plastic. There is a one-story brick addition at the rear that has a tall brick chimney with metal cap at the rear.

22. Architectural Style/Building Type: No Style

23. Landscaping or Special Setting Features:
N/A

24. Associated Buildings, Features, or Objects:
None

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate 1916-26 **Actual**
Source of Information: Historic Photographs

26. Architect: Unknown
Source of Information:

27. Builder/Contractor: Unknown
Source of Information:

28. Original Owner: Unknown
Source of Information:

29. Construction History (include description and dates of major additions, alterations, or demolitions):
The 1914 Sanborn map shows a different iron clad building on this site. This building appears on a 1926 photograph and the 1929 Sanborn map. Between 1929 and 1945 a one-story addition was constructed at the rear of the building.

30. Original Location: Yes **Date of Moves**

HISTORICAL ASSOCIATIONS

31. Original Use(s): Unknown Use

32. Intermediate Use(s) Commerce and Trade/Specialty Store/Gas Station

33. Current Use(s): Commerce and Trade/Specialty Store

34. Site Type(s): Commercial Building

35. Historical Background:

An earlier iron-clad building with a gable roof on this site served as a fire department hose house. The earlier building is shown on the 1914 Sanborn fire insurance map, while the current building appears on the 1929 map. Historic photographs of Salida from Tenderfoot Hill show that the building was erected between 1916 and 1926.

By 1930-31 this building appears to have been part of the Salida Service Station, which was addressed as 100-24 G Street. The Salida Service Station dates to about 1927. An advertisement for the Salida Service Station, a Texaco retailer, was published in the October 1927 "Booster Edition" of the Salida Mail. R.K. Young was listed as the proprietor. The station offered tires, batteries, accessories, vulcanizing, greasing, and complete lubrication service and pledged that "our modern tire shop is equipped to give you complete tire service and we guarantee every repair for the life of the tire."

The Salida Service Station, Roy K. Young, president, was still at this location (address as 100 G Street) in 1951. In 1961, Bill's Auto Body Services was located in this building. Bill Williams was the owner. The National Register nomination for Downtown Salida, prepared in 1983, stated that this was Kolbeck's Auto Service. Kolbeck's Gas Station was located to the north at today's 205 W. 1st Street.

36. Sources of Information:

Chaffee County Assessor records; Salida City Directories; Sanborn Insurance Maps; Russ Collman, Trails Among the Columbine (Denver: Sundance Publications, 1992), 218 and 247; Salida Downtown Historic District, National Register nomination, 27 November 1983; Salida Mail Booster Edition, 21 October 1927.

VI. SIGNIFICANCE

1. Local Landmark Designation: No

Date of Designation:

Designating Authority:

38. Applicable National Register Criteria:

- A. Associated with events that have made a significant contribution to the broad pattern of our history;
- B. Associated with the lives of persons significant in our past;
- C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possesses high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
- D. Has yielded, or may be likely to yield, information important to history or prehistory.

Qualifies under Criteria Considerations A through G (See Manual).

X Does not meet any of the above National Register criteria.

39. Area(s) of Significance:**40. Period of Significance:****41. Level of Significance:****42. Statement of Significance:**

This building is associated with the history of automobile-related services in downtown Salida and housed a service station for much of its history.

43. Assessment of Historic Physical Integrity Related to Significance:

Further research should be undertaken to determine the level of alteration to this building. The building was indicated as contributing to the district on a 1981 survey form.

VII. NATIONAL REGISTER ELIGIBILITY ASSESSMENT**44. National Register Field Eligibility Assessment:** Not eligible**45. Is there National Register district potential? Discuss.** N/A

This building is located within an existing National Register District, the Salida Downtown Historic District.

If there is NRHP district potential, indicate contributing status: N/A

46. If the building is in an existing NRHP district, indicate contributing status: Contributing**VIII. RECORDING INFORMATION****47. Photographic Reference(s):** 26: 13, 15, 17, 19.

Negatives Filed At: City of Salida

Photographer: Roger Whitacre

48. Report Title: Downtown Salida Historic Buildings Survey, 2001-02**49. Date(s):** September 2002**50. Recorder(s):** R.L. Simmons/T.H. Simmons**51. Organization:** Front Range Research Associates, Inc.**52. Address:** 3635 W. 46th Ave.**53. Phone Number(s):** (303) 477-7597

NOTE: Please attach a sketch map, a photocopy of the USGS quad map indicating the resource's location, and photographs.


Colorado Historical Society-Office of Archaeology and Historic Preservation

1300 Broadway, Denver, Colorado 80203 (303) 866-3395

Downtown Salida Historic Buildings Survey, 2001-02
Sketch Map




124 G Street, 5CF406.70



Downtown Salida Historic Buildings Survey, 2001-02
USGS Location Map

124 G St, 5CF406.70



Mosaic of extracts from U.S. Geological Survey, "Salida East, Colo.," and "Salida West, Colo.," (Denver, Colo.: U.S. Geological Survey, 1994).

