



ARCHITECTURAL/HISTORICAL COMPONENT FORM

IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

- 1) Resource No. 5CF274 2) Temp No. 63 3) Name Commercial Building
(apartments upstairs)
4) Address 100 blk. E. Sackett St 5) District Name Salida Commercial District
south side
I. INTEGRITY: 6) Condition: Good Fair Deteriorated
7) Original Use commercial property 8) Present Use commercial property
9) Original Site Moved Date(s) of Move: _____
10) Unaltered Altered Explain: _____

II. DESCRIPTION: 11) Building Materials brick/metal cornice

- 12) Construction Date 1890-1893 13) Architect/Builder unknown
(1890, 1893 Sanborn Perris Maps)
14) Architectural Style(s) n/a
15) Special Features/Surroundings: The building is located directly across
from Riverside Park

- 16) Archaeological Potential: Yes No Unknown Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce	
18) SUB-THEME	(appears empty, except for apts. on second floor)	
19) TYPES	commercial structure	

(Attach Photographs)

Frame Number 13
Roll Number CF4
Facade Orientation N

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

Within Salida, this two story brick structure is a fine intact example of late nineteenth century commercial architecture. The building is distinguished by a richly decorated bracketed cornice, four window openings on the second floor accented by rough cut stone lintels and sills, and a continuous lintel separating the upper floor from the storefront area. The storefront area displays the features common to nineteenth century commercial structures - a recessed entrance, flanking display windows, kickplates (panels beneath the display windows), and iron support columns. On this particular structure, a side entrance is also evident.

A saloon occupied the structure from 1893 to approximately 1914 when a Chinese laundry is listed as the occupant.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1893...1914 Sanborn Perris Maps

