

ARCHITECTURAL/HISTORICAL COMPONENT FORM



IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

1) Resource No. 5CF260 2) Temp No. 49 3) Name former Salida Drugs/The Closet
 4) Address 100 blk. F Street, east side 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good Fair Deteriorated

7) Original Use commercial property 8) Present Use commercial property

9) Original Site Moved Date(s) of Move: _____

10) Unaltered Altered Explain: Second floor windows modified; brick and wood siding over portions of lower facade; The building is currently being rehabilitated after a fire.

II. DESCRIPTION: 11) Building Materials brick

12) Construction Date c. 1883 13) Architect/Builder unknown
 (on 1883 Sanborn Perris Map)

14) Architectural Style(s) n/a

Special Features/Surroundings: Cornice, window, and storefront alignment continue the dominant pattern within the commercial district

16) Archaeological Potential: Yes No Unknown Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce		
18) SUB-THEME	Retail/Wholesale		
19) TYPES	commercial structure		

(Attach Photographs)

Frame Number	<u>18</u>
Roll Number	<u>CF3</u>
Facade Orientation	<u>W</u>

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

A two story brick commercial building which features a four part facade. On the second floor the paired segmental openings (these have been partially bricked in) are separated by narrow pilasters which rise to the roof line. Parallel rows of brick corbelling provide additional decorative details. At the storefront level, only minor alterations obscure the original features.

In 1883 a drug store, a clothing and dry goods store, and fruit market occupied the building.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1/ 1883 Sanborn Perris Map



SALIDA
Wholesale Agency
DRUGS

CLOSET
CLOTHING & ACCESSORIES

Sharpe's
READY-TO-WEAR