



ARCHITECTURAL/HISTORICAL COMPONENT FORM

IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

1) Resource No. 5CF271 2) Temp No. 60 3) Name Sign Store (Printers, Sign Painters)
4) Address 100 blk. North F 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good Fair Deteriorated

7) Original Use commercial property 8) Present Use commercial property

9) Original Site Moved Date(s) of Move: _____

10) Unaltered Altered Explain: brick over kickplates (panels beneath display windows)

II. DESCRIPTION: 11) Building Materials brick/metal cornice

12) Construction Date 1886 - 1890 13) Architect/Builder unknown
(1886, 1890 Sanborn Perris Maps)

14) Architectural Style(s) n/a

15) Special Features/Surroundings: see resource no. 5CF263

16) Archaeological Potential: Yes No Unknown Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce		
18) SUB-THEME	Trades		
19) TYPES	commercial structure		

(Attach Photographs)

Frame Number 10
 Roll Number CF4
 Facade Orientation W

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

A two story brick commercial building, which is part of a row of almost identical structures. The narrow building features the bracketed cornice that connects it to its neighbors, three segmental arch openings, and a continuous lintel separating the largely intact storefront from the upper story.

In 1890 a restaurant occupied this building.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1890 Sanborn Perris Map