



ARCHITECTURAL/HISTORICAL COMPONENT FORM

IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

1) Resource No. 5CF241 2) Temp No. 30 3) Name IOOF Lodge
4) Address 113 E. First St. 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good Fair Deteriorated

7) Original Use commercial property 8) Present Use commercial property

9) Original Site Moved Date(s) of Move: _____

10) Unaltered Altered Explain: Stucco over original brick facade.
Brick siding over kickplates (panels beneath display windows).

II. DESCRIPTION: 11) Building Materials brick

12) Construction Date 1887 (on bldg.) 13) Architect/Builder unknown

14) Architectural Style(s) n/a

15) Special Features/Surroundings: This building continues the cornice,
window, and storefront pattern displayed by a majority of the district
buildings.

16) Archaeological Potential: Yes No Unknown Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Social/Humanitarian		
18) SUB-THEME	Benevolent Societies		
19) TYPES	IOOF Building		

(Attach Photographs)

Frame Number 12
 Roll Number CF 2
 Facade Orientation N

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

Although the IOOF Building has been stuccoed, it retains its original features and thus plays a contributing role in the district. The building is characterized by four segmental arch bays which are arranged 1-2-1. The bays are double hung with a transom. At the storefront level, a lintel separates the commercial entrance from the upper floor. The storefront features a recessed entrance flanked by large display windows. A side entrance to the second story which housed the IOOF Hall is also visible.

In 1888 the lower floor housed a crockery shop; in 1890 a jewelry and fine goods establishment; in 1893 Salida's post office.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1888, 1890, 1893 Sanborn Perris maps

RECORDER M. Taylor

DATE 6-15-81

