

ARCHITECTURAL/HISTORICAL COMPONENT FORM



IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

1) Resource No. 5CF269 2) Temp No. 58 3) Name Master Printers/Storage
4) Address 114 E. First 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good Fair Deteriorated

7) Original Use commercial property 8) Present Use commercial property

9) Original Site Moved Date(s) of Move: _____

10) Unaltered Altered Explain: Stucco, brick siding over large
portion of lower facade

II. DESCRIPTION: 11) Building Materials brick/metal cornice

12) Construction Date 1886-1890 13) Architect/Builder unknown
(listed as "not complete" on 1886 Sanborn Perris Map)

14) Architectural Style(s) n/a

15) Special Features/Surroundings: Another building displaying the
dominant pattern of window, cornice, and storefront
alignment

16) Archaeological Potential: Yes No Unknown Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce		
18) SUB-THEME	Trades		
19) TYPES	commercial structure		

(Attach Photographs)

Frame Number 8
 Roll Number CF4
 Facade Orientation S

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

21) Historical Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

This two story brick commercial structure is distinguished by a stamped metal cornice and seven segmental arch bays which are accented by ornate window caps. (From an early photo in the Centennial publication, these window caps were a later addition). The central bay and the entrance below it are flanked by pilasters that rise to the cornice. A large part of the lower store front area has been altered through the addition of stucco.

In 1890 the structure housed a furniture and undertaking establishment - the Haight and Churcher Company - and a printing business.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1890 Sanborn Perris Map
2. Pasquale, Cynthia. 1980. 100 Years in the Heart of the Rockies.



RM
G
ROCKY
MOUNTAIN
GRAPHIC
REPRODUCTIONS

CONTINENTAL
TRAILWAYS
BUS