



ARCHITECTURAL/HISTORICAL COMPONENT FORM

**IMPORTANT:** USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

- 1) Resource No. 5CF227 2) Temp No. 16 3) Name C.G. Casuals/Great American T-Shirts  
 4) Address 126-132 F Street 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good  Fair  Deteriorated

7) Original Use commercial property 8) Present Use commercial property

9) Original Site  Moved  Date(s) of Move: \_\_\_\_\_

10) Unaltered  Altered  Explain: Original storefronts totally altered.  
Second story windows partially bricked in.

II. DESCRIPTION: 11) Building Materials brick/cut stone

12) Construction Date 1890 (on bldg.) 13) Architect/Builder unknown

14) Architectural Style(s) n/a

15) Special Features/Surroundings: The building's richly decorated cornice distinguishes it from its neighboring structures. The building itself continues the dominant patterns of the district.

16) Archaeological Potential: Yes  No  Unknown  Explain: \_\_\_\_\_

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	<u>Commerce</u>		
18) SUB-THEME	<u>Retail/Wholesale</u>		
19) TYPES	<u>commercial structure</u>		

(Attach Photographs)

Frame Number 19  
 Roll Number CF1  
 Facade Orientation E

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

This two story brick structure, named the Hively Block on the 1893 Sanborn map, is distinguished by a richly detailed cornice complete with brackets and metal roof cresting. On the second story the original paired bays have been partially bricked in and replaced by modern windows. The stone lintels and sills which highlighted the openings are still visible. Of special interest is the outside entrance on the north facade of the building. Although the street level entrance has been extensively altered, the windows lighting the stairway and the decorative pediment-like features above them are evident. On the ground floor the original storefronts have been totally modified.

In 1893 the building housed a clothing store and a dry goods store which also featured boots and shoes. Offices were on the second floor.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1893 Sanborn Perris Map



C-G CASUALS

WINDMILL  
FABRICATION

WINDMILL  
FABRICATION