

ARCHITECTURAL/HISTORICAL COMPONENT FORM



IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

1) Resource No. 5CF220 2) Temp No. 9 3) Name American Selco Inc.

4) Address 128 North F 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good Fair Deteriorated

7) Original Use commercial property 8) Present Use commercial property

9) Original Site Moved Date(s) of Move: _____

10) Unaltered Altered Explain: According to the assessor's card this structure was rebuilt in 1942. It has a new brick facade and a concrete block north wall

II. DESCRIPTION: 11) Building Materials brick/concrete block
1890-1893

12) Construction Date rebuilt in 1942 13) Architect/Builder unknown
(1890, 1893 Sanborn Perris maps)

14) Architectural Style(s) n/a

15) Special Features/Surroundings: The building is flanked by an alley (to the south) and an empty lot (to the north)

16) Archaeological Potential: Yes No Unknown Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce		
18) SUB-THEME	Professional Service		
19) TYPES	Commercial structure		

(Attach Photographs)

Frame Number	<u>11</u>
Roll Number	<u>CF1</u>
Facade Orientation	<u>E</u>

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

Although this one story brick structure was partially rebuilt in 1942, it plays a contributing role in the district. The building retains the features common to nearly all of the district's structures: a recessed entrance with flanking display windows and a transom window. The building is also characterized by simple brickwork patterns.

In 1893 a saloon occupied the structure.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1893 Sanborn Perris Map

