



ARCHITECTURAL/HISTORICAL COMPONENT FORM

IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

1) Resource No. 5CF219 2) Temp No. 8 3) Name Pinecone Antiques
4) Address 136 North F 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good Fair Deteriorated

7) Original Use commercial property 8) Present Use commercial property

9) Original Site Moved Date(s) of Move: _____

10) Unaltered Altered Explain: Storefront area modified - stone veneer, stucco, and modern windows added

II. DESCRIPTION: 11) Building Materials brick/cut stone

12) Construction Date c. 1883 13) Architect/Builder unknown
(on 1883 Sanborn Perris map)

14) Architectural Style(s) n/a

15) Special Features/Surroundings: See resource no. 5CF221

16) Archaeological Potential: Yes No Unknown Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	<u>Commerce</u>		
18) SUB-THEME	<u>Retail/Wholesale</u>		
19) TYPES	<u>commercial structure</u>		

(Attach Photographs)

Frame Number 10

Roll Number CF1

Facade Orientation E

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

A brick two story commercial structure featuring parallel stone stringcourses near the cornice, and three segmental arch openings highlighted by brick window hoods and cut stone sills. The original storefront has been altered, although the transom area and recessed entrances are still visible.

The structure housed a saloon (saloons were the most common business establishment on this block of F Street) until at least 1914 when a restaurant is listed as occupying the building.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1883...1914 Sanborn Perris Maps



ANTIQUE

BUY, SELL & TRADE

