



ARCHITECTURAL/HISTORICAL COMPONENT FORM

IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

1) Resource No. 5CF303 2) Temp No. 92 3) Name Cranberry Kitchen
4) Address 137 E. First 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good Fair Deteriorated

7) Original Use commercial property 8) Present Use commercial property

9) Original Site Moved Date(s) of Move: _____

10) Unaltered Altered Explain: _____

II. DESCRIPTION: 11) Building Materials brick/metal cornice

12) Construction Date 1883-1886 13) Architect/Builder unknown
(1883, 1886 Sanborn Perris Maps)

14) Architectural Style(s) n/a

Special Features/Surroundings: The building continues the pattern of cornice, window, and storefront alignment evident in the district

16) Archaeological Potential: Yes No Unknown Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce		
18) SUB-THEME	Retail/Wholesale		
19) TYPES	commercial structure		

(Attach Photographs)

Frame Number 11
 Roll Number CF6
 Facade Orientation N

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

Within Salida, this two story brick building provides an intact example of late nineteenth century commercial architecture.

The structure is characterized by a bracketed metal cornice, two segmental arch openings accented by brick window hoods (the large openings are composed of paired bays), and a bracketed lintel separating the second story from the storefront area. Below the lintel is a transom window stretching the width of the building, a recessed entrance framed by display windows and a side entrance.

According to the 1886 Sanborn Perris Map, lodgings were available in this building. By 1890, a barber shop was added.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1886, 1890 Sanborn Perris Maps



GOOD
FOOD & SODA

CLOSED

DIP