



ARCHITECTURAL/HISTORICAL COMPONENT FORM

IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

1) Resource No. 5CF273 2) Temp No. 62 3) Name Victoria Tavern
4) Address 143 North F 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good Fair ___ Deteriorated ___

7) Original Use commercial property 8) Present Use commercial property

9) Original Site Moved ___ Date(s) of Move: _____

10) Unaltered ___ Altered Explain: Windows on lower level floor
modified - brick and metal siding added

II. DESCRIPTION: 11) Building Materials brick

12) Construction Date 1898-1904 13) Architect/Builder unknown
(1898, 1904 Sanborn Perris Maps)

14) Architectural Style(s) n/a

5) Special Features/Surroundings: This building, located across from
Riverside Park at the northern edge of the proposed historic
district, is a significant corner structure.

16) Archaeological Potential: Yes ___ No Unknown ___ Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce	
18) SUB-THEME	Retail/Wholesale	
19) TYPES	commercial structure	

(Attach Photographs)

Frame Number 12
Roll Number CF4
Facade Orientation W

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

- 20) Architectural Significance:
- Represents work of a master
 - Possesses high artistic values
 - Represents a type, period, or method of construction

- 21) Historical Significance:
- Associated with significant persons
 - Associated with significant events or patterns
 - Contributes to the significance of an historic district

The structure currently housing the Victoria Tavern is a two story brick building featuring a corbel table at the cornice line. On the street facade the upper story bays are arranged 3-4-3 and separated by pilasters. These openings and those on the north facade are demarked by cut stone sills. The building has a corner entrance and three entrances on F Street.

A grocery, meat market, and hall occupied the building in 1904. Five years later part of the building was empty, while a saloon and grocery store occupied the remaining sections.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1904, 1909 Sanborn Perris Maps

