



ARCHITECTURAL/HISTORICAL COMPONENT FORM

IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

- 1) Resource No. 5CF249 2) Temp No. 38 3) Name Amaranth
 4) Address 229 F Street 5) District Name Salida Commercial District
 I. INTEGRITY: 6) Condition: Good Fair Deteriorated
 7) Original Use commercial property 8) Present Use commercial property
 9) Original Site Moved Date(s) of Move: _____
 10) Unaltered Altered Explain: wood sign over transom area

- II. DESCRIPTION: 11) Building Materials brick
 12) Construction Date 1886-1890 13) Architect/Builder unknown
 (1886, 1890 Sanborn Perris Maps)
 14) Architectural Style(s) n/a
 15) Special Features/Surroundings: See Resource no. 5CF248

- 16) Archaeological Potential: Yes No Unknown Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce		
18) SUB-THEME	Retail/Wholesale		
19) TYPES	commercial structure		

(Attach Photographs)

Frame Number 7
 Roll Number CF3
 Facade Orientation W

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

21) Historical Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

A two story brick commercial building characterized by a corbel table somewhat below the cornice line, three narrow segmental arch bays with small window caps, and an "almost intact" storefront -- only the transom area has been altered. Below the transom area is a recessed entrance accented by sidelights and its own transom. Of interest are the kickplates (the panels beneath the display windows) which are wood - originally the most common material for these panels. (on most commercial buildings the kickplates have been covered by various other materials).

A grocery store occupied the building in 1890. A printing and photo shop followed (a sign for Hay Photos is on the north facade of the building).

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1890, 1898 Sanborn Perris Fire Insurance Maps



amaranth

All Kids Clothing
ON SALE