

ARCHITECTURAL/HISTORICAL COMPONENT FORM



IMPORTANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR RECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR RECORDING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES.

1) Resource No. 5CF263 2) Temp No. 52 3) Name PT's Polish Corner

4) Address 100 blk. North F east side 5) District Name Salida Commercial District

I. INTEGRITY: 6) Condition: Good Fair Deteriorated

7) Original Use commercial property 8) Present Use commercial property

9) Original Site Moved Date(s) of Move: _____

10) Unaltered Altered Explain: stone and wood siding obliterates the lower facade

II. DESCRIPTION: 11) Building Materials brick/metal cornice

12) Construction Date north half-1886-1890 13) Architect/Builder unknown
(1886, 1890, 1893 Sanborn Perris Maps)

14) Architectural Style(s) n/a

15) Special Features/Surroundings: A row of buildings (resource nos. 5CF270-272 in addition to these structures) which are almost identical in design. Common features include a continuous metal cornice connecting all structures, segmental arch bays, and a continuous lintel above the storefront areas.

16) Archaeological Potential: Yes No Unknown Explain: _____

III. CULTURAL ACTIVITIES: Key the resource type (ie: house, barn, shed, school, church, etc) to the cultural activity theme and sub-theme category associated with it.

17) THEME	Commerce		
18) SUB-THEME	Retail/wholesale		
19) TYPES	commercial structure		

(Attach Photographs)

Frame Number 21
Roll Number CH 3
Facade Orientation W

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

- Represents work of a master
- Possesses high artistic values
- Represents a type, period, or method of construction

21) Historical Significance:

- Associated with significant persons
- Associated with significant events or patterns
- Contributes to the significance of an historic district

These two brick buildings, currently housing one business establishment, were constructed at the end of the nineteenth century (the north half, 1886-1890; the south half 1890-1893). They are similar two story commercial structures, with a continuous bracketed cornice connecting them. A lintel above the now-altered storefront area is also evident. The southern portion has three segmental arch bays highlighted by radiating voussoirs. The northern portion has two segmental arch bays also accented by voussoirs. A corbel table underlines the metal cornice.

In 1890 a meat market occupied the northern half of the building. In 1893 the connecting structure housed a saloon.

22) List Any Associated Cultural Group: n/a

V. REFERENCES:

1. 1890, 1893 Sanborn Perris maps



Band Box
COIN OPERATED
LAUNDRY

PT'S POLISH
CORNER

